

GM Vehicle Inquiry System

Summary

[Home](#) - [Summary](#) - [Claim History](#) - [Vehicle Build](#) - [Vehicle Component](#) - [Delivery Information](#) - [Dealer Information](#) - [Service Contract](#) - [Warranty Block](#) - [Branded Title](#)

[Help](#)

VIN :	2GCFC135791112469
--------------	-------------------

VEHICLE INFORMATION

Merchandising Model :	CC10543 -2009 SILVERADO 1500 2WD CREW CAB 1HY	Warranty Start Date :	02/27/2009
BARS Order Type :	81 - DEALER USED CAR (CVMS USE)		
Delivering Dealer :	N/A	Selling Source :	N/A
		Site Code :	N/A
		Business Associate Code :	N/A
Service Contract :	No	Branded Title :	No
		Warranty Block :	No
		PDI Status :	Paid

REQUIRED FIELD ACTIONS

Type	Number	Description	Posted Date	Status
RC	09102	BATTERY CHARGE READING INCORRECT - REPROGRAM MODULE	N/A	Closed

SERVICE INFORMATIONAL ITEMS

Type	Number	Description	Posted Date	Status
EI	08310	POOR A/C PERFORMANCE, NOT COLD ENOUGH, COMPRESSOR NOISE. REF. TSB 08-01-39-010	08/14/2009	See Bulletin
EI	09081	BODY MOUNTED WEATHER STRIP REPLACEMENT (REF. TSB 09-08-64-012)	04/01/2009	See Bulletin
EI	09085	FRONT SUSPENSION CLUNK, SQUEAK, RATTLE POPPING OR CREAK (REF TSB 09-03-08-006)	04/22/2009	See Bulletin
EI	09086	AUTO HVAC INOP/AUTO HVAC CONTROL REPL/REPROG. RPO CJ2 ONLY (TSB 09-01-39-004)	05/06/2009	See Bulletin
EI	09088	FRT OR RR DOOR WINDOW BINDS, MOVES SLOW/NOISY/OR INOP (TSB 09-08-64-015)	04/24/2009	See Bulletin
EI	09113	FRONT WINDSHIELD WIPER FUNCTION(REF. TSB 09-08-43-002)	05/15/2009	See Bulletin
EI	09115	POOR A/C PERFORMANCE, A/C COMPRESSOR NOISE (TSB 09-01-39-006)	05/13/2009	See Bulletin
EI	09117	RADIO INOPERATIVE OR NO DISPLAY(REF. TSB 09-08-44-012)	05/15/2009	See Bulletin
EI	09142	PAINT APPEARANCE, DIRT/ORANGE-PEEL/THIN,BLEED THRU/RUNS (REF. PIE 0005)	08/12/2009	See Bulletin
EI	09212	HVAC VENT TEMPERATURE DIFFERS FROM CONTROL SETTINGS (REF. PIE 0011)	08/31/2009	See Bulletin
		REMOTE KEYLESS ENTRY (RKE) REPROGRAMMING (REFERENCE PIE		See

EI	09215	0014)	09/17/2009	Bulletin
----	-----------------------	-------	------------	----------

ON STAR AND XM SATELLITE RADIO INFORMATION

OnStar Equipped	Yes	OnStar Status	Inactive	Refer to Help page for details or: go to OnStar Online Enrollment (located on the "OnStar" tab in GM InfoNET) or (888)ONSTAR1 (888) 667-8271.		
XM Equipped	Yes	XM Radio ID	E88L12MT	XM Status	Inactive	Refer to Help page for details or: www.xmradio.gm.ca or Dealer Hotline 1.877.GET.XMST (1-877-438-9677).

APPLICABLE WARRANTIES

Description	Effective Date	Effective Odometer	End Date	End Odometer
36/36000 BUMPER TO BUMPER LIMITED WARRANTY	02/27/2009	0 miles	02/27/2012	36000 miles
72/100000 SHEET METAL COVERAGE RUST THROUGH LIMITED WARRANTY	02/27/2009	0 miles	02/27/2015	100000 miles
60/100000 POWERTRAIN COVERAGE LIMITED WARRANTY	02/27/2009	0 miles	02/27/2014	100000 miles
96/80000 FEDERAL EMISSION CATALYTIC CONV. AND PCM	02/27/2009	0 miles	02/27/2017	80000 miles
96/100000 HYBRID LIMITED WARRANTY	02/27/2009	0 miles	02/27/2017	100000 miles
84/70000 CALIFORNIA SELECT COMPONENT	02/27/2009	0 miles	02/27/2016	70000 miles
36/50000 CALIFORNIA EMISSIONS	02/27/2009	0 miles	02/27/2012	50000 miles

CLAIM HISTORY

R.O Date	R.O Number	Type	Labor Operation	Odometer Reading
08/28/2009	091027	F	Z7200 - CORPORATE PARTS RETURN REIMBURSEMENT	391 miles
08/04/2009	090395	#	J6380 - SENSOR, OXYGEN (CATALYST MONITORING) - REPLACE	391 miles
07/09/2009	089741	#	V2095 - 09102 - REPROGRAM SEQ EBCM/HCP/ECM/TCM/BECD	18 miles
12/16/2008	A12469	I	Z7000 - PRE-DELIVERY INSPECTION - BASE TIME	0 miles